


a Front edge of tooth
b Rear edge of tooth
c 2 missing teeth (gap)
h Crankshaft position sensor signal
x Wiring diagram representation of crankshaft position sensor with 2-pin coax plug contact
L5 Crankshaft position sensor